



LOC I-TUN 109.9	APP CRS 274°	Rwy Idg TDZE Apt Elev 7201 770 782
---------------------------	------------------------	--

ILS or LOC RWY 27
BISHOP INTL (F'NT)

DME or RADAR required for procedure entry. DME or RADAR required.			MALSR 	MISSED APPROACH: Climb to 2600 on FNT VORTAC R-275 direct SELFY/FNT VORTAC 10.6 DME/RADAR and hold.	
	DME from FNT VORTAC. Simultaneous reception of I-TUN and FNT DME required. For inop ALS, increase S-LOC 27 Cat A/B visibility to 1 SM, and Cat C/D visibility to 1½ SM.				
ATIS 133.15	GREAT LAKES APP CON ★ 118.8 257.9	FLINT TOWER ★ 126.3 (CTAF)  257.9	GND CON 121.9	CLNC DEL 121.75	UNICOM 122.95



2600 ↑ *LOC only.	FNT R-275	SELFY FNT <u>10.6</u> RADAR			HARRO FNT <u>10</u> RADAR	One Minute Holding Pattern
*LOC only.						
CATEGORY		A		B	C	D
S-ILS 27		970-½ 200 (200-½)				
S-LOC 27		1260-½ 490 (500-½)		1260-1 490 (500-1)		
	1260-1 478 (500-1)		1300-1 518 (600-1)		1300-1½ 518 (600-1½)	
	1260-1 478 (500-1)		1300-1 518 (600-1)		1520-2¼ 738 (800-2¼)	