




HI-VOR Z or TACAN Z RWY 26

VORTAC TUL 114.4 Chan 91		APCH CRS 262°	Rwy Idg TDZE Arpt Elev 7376 652 678	[USAF]	TULSA INTL (KTUL)	
DME required *When ALS inop, increase CAT CDE vis to 1¼ miles. **CAT E circling not authorized S of Rwy 8-26.				MALSR A5	MISSED APPROACH: Climbing left turn to 2600 on heading 220° and TUL VORTAC R-238 to KEVIL/TUL 25.4 DME and hold.	
ATIS 124.9 377.2	APP CON 124.0 338.3 175° - 354° 119.1 351.8 355° - 174°		TOWER 121.2 310.8 Rwy 18L-36R, 8-26 118.7 257.8 Rwy 18R-36L	GND CON 121.9 348.6	CLNC DEL 134.05 284.7	ASR



EMERG SAFE ALT 100 NM 4500



HI-VOR Z or TACAN Z RWY 26